

Subject : Elevator drive

Affected : Sailplanes model "Club-Libelle 205" } F.R.G. Type Certif.
"Hornet" } No. 304
"Mosquito" } F.R.G. Type Certif.
"Glasflügel 304" } No. 318
- all variants, all serial numbers

Urgency : Action step 1: Daily, prior to first flight
Action step 2: Not later than April 30th, 1988

Reason : Difficulties in the control of the sailplane were encountered when an elevator drive bracket broke on one side in flight.

Actions : 1. On sailplanes having an earlier type elevator drive bracket (without reinforcements identified as part (5), modif. 2, on the drawing shown overleaf), a visual inspection for possible cracks in the bracket arms must be carried out. It must also be checked that the bracket arms are not twisted out of line.
2. On sailplanes having an earlier type elevator drive bracket (without reinforcements), the bracket must either be reinforced according to the drawing shown overleaf or be replaced by a reinforced bracket. When the tailplane is re-assembled, it must be made sure that the correct number of spacing washers are fitted between the bracket arms and the ball bearings (tag washers when removing the bracket).

Weight : The effect is negligible

Materials : The reinforced elevator drive bracket, manufactured according to drawing No. 205-33-9 (modification 2) or the additional metal strips with welding wire 1.7734.2 may be obtained from:
Hansjörg Streifeneder
Glasfaser-Flugzeug-Service GmbH
Hofener Weg
7431 Grabenstetten
Federal Republic of Germany



Note : Welding according to drawing No. 205-33-9 (modification 2) must be done by a licensed aircraft welder.
Accomplishment of action 1 must be done by a skilled person.
Accomplishment of action 2 must be entered in the sailplane's log by a licensed inspector.

Grabenstetten, January 12th, 1988

LBA-approved:

The German original of this Technical Note has been approved by the LBA under the date of 3. Feb. 1988 and is signed by Mr. ... Frier The translation into English has been done by best knowledge and judgement. In any case of doubt the German original is authoritative.

Issued: *F. Streifeneder*
(Streifeneder)



Schnitt A-B
Section A-B

Fitting drilled with drilling jig
Ream drilled hole 10H7 with device
after welding
For dimensions see DIN 7168 medium range

Beschlag mit Vorrichtung gebohrt, Bohrungen 10H7
in Vorrichtung parallel aufgerieben (nach Schweißung)

Bei nicht tolerierten Maßfen gilt
DIN 7168 Genauigkeitsgrad mittel.

TIG welding with filler metal 1.7734.2 ge-
schwellig. Grundiert mit Wash-Primer 42002 + Härter
40018. Decklackierung mit Nitro-Lack grau RAL 7003,
RAL 7003 or cadmium-plated

②	6	Blech	sheet metal	1.7734.4	40 x 4 x 1,5
①	5	Blech	sheet metal	1.7734.4	28 x 8 x 1
	4	Rohr	tube	ST 35 BK	14 x 337 DIN 2391
	3	Rohr	tube	1.7734.4	20 x 173 x 1,5
	2	Blech	sheet metal	1.7734.4	15 x 8 x 1,5
	1	Blech	sheet metal	1.7734.4	173 x 78 x 2
	Pos. Nr.	Stückzahl	Benennung	Werkstoff	Zahn Nr./Abmaß, Gewinde
	1974	Tag	Name		
	Gez.	1671	102		
	Gepr.		(u.p.)		
	Norm				
	Material				
	1:1				



GLASFLÜGE
ING. EUGEN HANLE
SCHLATTSTALL KR. NÖRTING

HR - Antrieb
Elevator drive bracket

205-33-9

Produced	10.83	H. Str.	
Wachsfertigung ab 1983	13.6.75	U. W. S.	
Abw.Nr.			
Betr. W. Nr.			
Pos. 6 nachgetragen	added		
Pos. 5 nachgetragen	added		
Änderung			
Datum			
Name			
Antr. Nr.			