

Subject: Airbrake drive (gear) inside wing panels

Affected: Sailplanes model „Standard Libelle 201“ and
„Standard Libelle 201b“
F.R.G. Data Sheet No. 251
all serial numbers.

Urgency: None – optional installation

Reason: Optional use of a metal gear as per drawing
No. 301-56-12 / 2 (up to S/N 119) or drawing
No. 201-56-40 (for S/N 120 and up)
instead of the standard GFRP gear installed.

Actions: Procurement of a complete conversion Kit including working
instructions for the serial number concerned.

Material: Kit and instruction may be obtained from

Glasfaser-Flugzeug-Service GmbH
Hansjörg Streifeneder
Hofener Weg
72582 Grabenstetten
Telefon 07382 / 1032 Fax 07382 / 1629
http://www.streifly.de e-mail: streifly@aol.com

Note: The proper accomplishment of the actions is to be certified by a
licensed inspector and and must be entered in the sailplane log book.

Weight: No change

C/G position: No change

Grabenstetten, May 10, 2002

Issued: *H. Streifeneder*
Hansjörg Streifeneder

LBA-approved:

The German original of this Technical Note has been
approved by the LBA under the date of **13.08.02**,

and is signed by Mr. *U. Kapp*
The English translation has been done by best
Knowledge and judgement.