

**Subject:** Airbrake drive (gear) inside wing panels

**Affected:** Sailplanes model „Libelle H301“ and  
„Libelle H301B“  
F.R.G. Data Sheet No. 251  
S/N 7 and up

**Urgency:** None – optional installation

**Reason:** Optional use of a metal gear as per drawing  
No. 301-56-12 / 2  
instead of the standard GFRP gear installed.

**Actions:** Procurement of a complete conversion Kit including working  
instructions for the serial number concerned.

**Material:** Kit and instruction may be obtained from  
  
Glasfaser-Flugzeug-Service GmbH  
Hansjörg Streifeneder  
Hofener Weg  
72582 Grabenstetten  
Telefon 07382 / 1032 Fax 07382 / 1629  
http://www.streifly.de e-mail: streifly@aol.com

**Note:** The proper accomplishment of the actions is to be certified by a  
licensed inspector and and must be entered in the sailplane log book.

**Weight:** No change

**C/G position:** No change

Grabenstetten, May 10, 2002

Issued: *H. Streifeneder*  
Hansjörg Streifeneder

LBA-approved:

The German original of this Technical Note has been  
approved by the LBA under the date of 13.08.02  
and is signed by Mr. *U. Kopp*  
The English translation has been done by best  
Knowledge and judgement.