

<u>Subject</u>	:	TOST nose tow release mechanism	
<u>Affected</u>	:	Sailplanas model	Technical Note No.
		Libelle H 301 and H 301 B	34
		Standard Libelle H 201, 201 B, 202, 203, 204	28
		Club Libelle 205	17
		Hornet and Hornet C	14
		Mosquito and Mosquito B	15
		Glasflügel 304 and 304/17	5
		Falcon	2
		Kestrel	22
		BS 1	6
		Glasflügel 604	4

Urgency : None, optional use as a replacement or for retro-fitting

Reason : Optional use of the TOST nose tow release model "E 85" as a substitute for models "E 72" and "E 75", which are no longer in production. As there is hardly any difference in external shape, the existing release is easily replaced.

Actions :

1. The new model "E 85" may be installed/retro-fitted whenever necessary.
2. The TOST Operating Manual (Issue of March 1989) must be observed when installing/retro-fitting a nose tow release model "E 85" and this Technical note is to be inserted in the Flight & Service Manual or the Maintenance Manual.
 The actions may be carried out by a skilled person, their accomplishment must be entered in the sailplanes's log book by a licensed inspector.

Grabenstatten, March 8th, 1990

LBA-approved:



09. Mai 1990

u. M. 11

Issued:

H. Streifeneder

(H. Streifeneder)