

Subject: Deviation from german type certificate for serial numbers to be licenced in the Netherlands.

Affected: Model "Club Libelle".

Urgency: Until first inspection.

Action: 1. In the canopy an obstacle deflector must be installed according to draw. No. 205-14-48.
2. In the flight manual the acrobatic manoeuvre "Positive Looping" is to be deleted and replaced by:
"Positive looping not allowed"

Weight and balancy: The balancing during first inspection is done with installed obstacle deflector.

Remarks: In the first inspection report must be certified:
"TM 205-13 carried out"

Lenningen, den 20.08.1980

(Signed: Martin Hansen)