

H. Streifeneder
Glasfaser-Flugzeug-Service GmbH
Hofener Weg
D-72582 Grabenstetten

Technical Note

201-27 (202, 203, 204)
205-17, 206-14
301-34, 303-15, 304-5
401-21, Falcon Nr.2

Subject: Elevator actuating bracket

Effectivity: All serial numbers:
Models H 301 Libelle, H 201 Standard Libelle, H 202, H 203, H 204, Club Libelle 205,
Hornet, Mosquito, Glasflügel 304, Falcon, Kestrel

Urgency: None.

Reason: Use of a bracket as per drawing no. 201-33-4 instead of former bracket types permissible.

Actions: In case of elevator actuating exchange use following procedure:
Unscrew the 6 screws on the elevator actuating bracket. Pay attention to the type and number
of washers at each bolt. Mark position precisely!
Install new actuating bracket including the washers on the same position.
Tighten screws carefully and check free motion of the elevator.

Material: Elevator actuating bracket according to drawing no. 201-33-4 is available from

Hansjörg Streifender
Glasfaser Flugzeug Service GmbH
Hofener Weg
D-72582 Grabenstetten


Weight and balance: Not affected.


Remarks: Actions mentioned above may be done and entered in the aircraft's log book by a skilled
person.

Grabenstetten, den 27. Februar 1990

LBA-approved:
(Frieß, 26. April 1990)

H. Streifeneder
H. Streifeneder




 25. April 1990

5	2	Blech	1.7734.4	30 x 8 x 1.5
4	2	Blech	1.7734.4	15 x 8 x 1.5
3	1	Rohr	1.7734.4	18 x 2 x 106
2	2	Rohr	1.7734.4	14 x 3 x 30
1	2	Blech	1.7734.4	201-33-3-4
Pos.Nr.	Stückz.	Benennung	Werkstoff	Zeichn.Nr. / Abmessung



1:1

Höhenruderantrieb "201"
 gilt auch für 401

201-33-4

22.02.1990

F. Stefeneder