

Glasfaser-Flugzeug-Service GmbH Hansjörg Streifeneder Hofener Weg 72582 Grabenstetten	<u>TECHNICAL NOTE NO. 401-28</u>	Page No. 1 No. Of pages 1
---	----------------------------------	------------------------------

Subject:	Extension of service life
Affected:	Sailplane model „Kestrel“ F.R.G. Type Certificate No. 276 All serial numbers
Compliance:	Before reaching a total service life of 6000 hours, however not later than June 30 th , 2006
Reason:	The results of cyclic loading tests carried out on wing spars justify the extension of the service life of FRP sailplanes and motor gliders to 12000 hours, provided that the airworthiness of each individual aircraft is evidenced by a special multi-stage inspection program carried out in compliance with supplementary instructions of the Flight- and Operations Manual.
Actions:	The Flight- and Operations Manual is to be supplemented by - Page No.33 and 34 titled „Inspection procedures for extension of the service life“ and the table of contents on page No.2 is to be amended accordingly.
Remarks:	Page N;33 and 34 of the Flight- and Operations Manual are available from : Hansjörg Streifeneder Glasfaser-Flugzeug-Service GmbH DE.21G.0080 und DE.145.0100 Hofener Weg D-72582 Grabenstetten Tel.: +49 (0)7382 1032 Fax.: +49 (0)7382 1629 www.streifly.de
Note:	The accomplishment is to be entered into the aircraft log book by a licensed inspector.
Lenningen, Oct. 15 th , 2005 Issued:..... (Streifeneder)	EASA approved: