

Glasfaser-Flugzeug-Service GmbH Hansjörg Streifeneder Hofener Weg 61 72582 Grabenstetten	Technical Note TN 401-23	Identification Sheet Nr. 276
---	-----------------------------	---------------------------------

Subject:	Continuous canopy with pop-up mechanism
Affected:	Glider type „Kestrel“
Urgency:	None, optional
Reason:	None, optional
Actions:	<ol style="list-style-type: none"> 1. Conversion according to the following technical drawings as per drawing list: <ul style="list-style-type: none"> • 401-14-50, 401-14-55, 401-14-60 through 401-14-77, as well as possibly 401-16-5 2. Modification of flight and operations manual
Documents and Material:	<ol style="list-style-type: none"> 1. Drawings as per drawing list 401-14-50, 401-14-55, 401-14-60 through 401-14-77, as well as possibly 401-16-5
Notes:	<ol style="list-style-type: none"> 2. Modified flight manual pages 9 and 11 <p>The conversion may only be carried out at the company:</p> <p style="text-align: center;"> Glasfaser-Flugzeug-Service GmbH DE.21G.0080 und DE.145.0100 Hofener Weg 61 D-72582 Grabenstetten Tel.: +49 (0)7382 1032 Fax.: +49 (0)7382 1629 www.streifly.de </p> <p>Proper implementation of the measures mentioned above must be certified by an in-house Class 3 inspector for a major change.</p> <p>The correction of the manual is to be entered on page 1a.</p>

Grabenstetten, May 13 th 1993 Issued:  Glasfaser-Flugzeug-Service H. Streifeneder	<p><u>The technical content to this Technical Note has been approved by the LBA:</u></p> <p>Date: <u>June 08th 1993</u></p>
--	--